

Department of Energy

ROCKY FLATS PROJECT OFFICE 12101 AIRPORT WAY, UNIT A BROOMFIELD, COLORADO 80021-2583 SEP 2 1 2005

05-DOE-00564

Mr. Carl Spreng Rocky Flats Cleanup Agreement Project Coordinator Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Dear Mr. Spreng:

Please find enclosed the additional information requested by Mr. David Kruchek, Colorado Department of Public Health and Environment, for the Building 707 Closure Project, a Type 3 Facility. Also included are figures that show the disposition of the asbestos piping associated with Building 709.

Questions may be directed to Rich Schassburger, Rocky Flats Project Office, at (303) 966-4888.

Sincerely,

John J. Rampe, Director RFPO Project Management

Enclosure

cc w/o Encl.:

S. Nesta, K-H, RISS Env

J. Heber, K-H RISS D&D

K. Wiemelt, K-H RISS D&D

cc w/Encl.:

D. Kruchek, CDPHE

M. Aguilar, USEPA

D. Abelson, RFCLOG

K. Korkia, RFCAB

Administrative Record



ADMIN RECORD

1) Please provide a figure identifying all removed and remaining building structures. Neither Fig 5, 6, or 7 provide the information requested. Please provide a figure that specifically identifies the remaining structures or parts of structures, and which have been removed.

Figure 5 shows the buildings in the 707 cluster and all structures have been removed except for the footers (west side) of B707, as depicted on Figure 7.

2) Fig 5 appears to indicate that all of B707 and 731 have been removed, and the rest of the building slabs in this cluster remain. Please fix or provide another figure that properly identifies the remaining and removed infrastructure associated with all buildings in the B707 Cluster.

Figure 5 modified to show that all of the buildings in the cluster have been demolished and removed. The only exception is 707 footers as noted on Figure 7.

3) Fig 6 - Please modify this figure to move the info boxes out of the area of interest, and please show all of the infrastructure/utility isolations associated with all of the buildings discussed in this Report. B778 is not identifiable, nor are the other buildings 707S, 708, 709, 711, 711A, 718, 731, or 732.

Completed, and enclosed.

4) Fig 7 - Please properly identify what this figure is supposed to show. Only the southern portion of B707 is shown on this figure. Where is B778 and the other buildings?


As stated above this figure shows the eastern portion of 707 building that was removed. This map does not address any other buildings in the cluster and this is all of the building it does show.


5) Section 1.3 - It appears to be implied that all of the building structures were removed except for the footers. But there is no specific description of what was removed and what remains of each building. Please provide a specific description of the removed and remaining structures for each of the buildings included in this Report.


See Figure 7 for Building 707.

6) Section 5 - Please expand this discussion to properly describe the infrastructure removed and remaining for all of the buildings included in this Report. In the 4th paragraph there is a discussion of the remaining asbestos piping under B709 and states this is shown on Fig 6, yet neither B709 nor this piping is identified on Fig 6. In the 5th paragraph it is stated that Fig 7 shows the remaining building foundations, yet Fig 7 appears to only show something associated with part of B707 (and it is not apparent what this figure is trying to show).

See responses to previous comments. Information concerning asbestos piping is shown on additional figures provided with this comment response.







5/4